

RPII Inspector Issued Report

Issued by: Elliotts Inspections

Issued 21/11/2025

RPII Reg Number: AI0223

Place of Inspection: On site at customer location

Unique Report Number: 105



SPENCER ELLIOTT
Certificate Number: AI0223



Unit Details

Description: front slide 3d xmas themed castle

Manufacturer: airquee

Size (m): Width: 3.7 Length: 4.5 Height: 3.0

Serial: 55159

Unit Type: front slide a-frame

Unit Owner: party time inflatables

User Height/Count

Containing Wall Height: 0.6m

Comment: Lowest wall height taken from adjacent platform.

Tallest Platform Height: 1.4m

Comment:

First Metre of Slide Height: 0.6m

Comment: Slide Combi Applicable - Highest 750 mm of the slope (contai

Remaining Slide Wall Height: 0.6m

Comment: Slide Combi Applicable - Remainder of the slope at least 300

Permanant Roof Fitted: True

Comment: Slide Combi Applicable - Yes, user is forced to crouch or si

Tallest User Height: 1.8m

Comment: Calculated using lowest containing wall height minus the pla

Internal Play Area Length: 2.2m

Comment:

Internal Play Area Width: 2.7m

Comment:

Negative Adjustment: 0m

Comment: Approx square metre are taken by obstacles, biff bash, mound

Users @ 1.0m: 6 Users @ 1.2m: 5

Users @ 1.5m: 4 Users @ 1.8m: 4

Slide

Slide Platform Height: 1.4m

Comment: Slide Combi Applicable - Platform height less than 1.5m and

Containing Wall Height: 0.6m

Comment: Slide Combi Applicable - Highest 750 mm of the slope (contai

First Metre Slide Wall Height: 0.6m

Comment: Slide Combi Applicable - Highest 750 mm of the slope (contai

Remaining Slide Wall Height: 0.6m

Comment: Slide Combi Applicable - Remainder of the slope at least 300

Perm Slide Roof Fitted: True

Comment: Slide Combi Applicable - Yes, user is forced to crouch or si

Steps/Clamber Netting Pass/Fail: True

Comment: Not monofilament, no entrapment and at least 12mm diameter,

Slide Run Out: 1.0m

Slide Run Out Pass/Fail: True

Comment: Slide Run-out is at least 50% of slide platform height.

Slip Sheet Integrity Pass/Fail: True

Comment: Slip sheet has no tears, causes no entrapment and is securel

Structure

Seam Integrity Pass/Fail: True

Comment: Secure and no loose stitching.

Lock Stitching Pass/Fail: True

Comment: Lock stitching used.

Stitch Length: 4mm

Stitch Length Pass/Fail: True

Comment: Stitching between 3mm - 8mm

Air Loss Pass/Fail: True

Comment: No significant air loss or holes.

Walls and Turrets Vertical Pass/Fail: True

Comment: Walls Vertical and gradient no greater than +5%

Sharp/Square/Pointed Edges Pass/Fail: True

Comment: No sharp or pointed edges.

Blower Tube Distance: 1.25m

Blower Tube Pass/Fail: True

Comment: Inflate blower tube is at least 1.2m from edge of cone to in

Unit Stable Pass/Fail: True

Comment: Unit is stable.

Evacuation Time: 30s

Evacuation Time Pass/Fail: True

Comment: Evacuation time sufficient for intended users to exit safely

Risk Assessment

The suitability of all materials used in manufacturing should be taken from conformity reports. Where not available these should be requested from the manufacturer/importer.

Safety aspects should be taken from the user manual provided by the manufacturer. If not provided then this should be requested or created by the controller.

Not to be used in wind speeds in excess of 38Kph.

A competant adult should supervise the inflatable and users at all times.

All anchor points to be used at all times.

Testimony: I certify that the equipment identified above was inspected and complied with the safety criteria required using all relevant sections of the European Standard EN 14960:2019 on the above date.

Result: Passed Inspection

The software used to generate this report was made by Spencer Elliott.